

This diagram shows an exploded perspective view of a mechanical assembly. The components are numbered as follows: 10 is a base cylindrical part; 11 is a middle cylindrical part; 12 is a C-shaped bracket; 13 is another C-shaped bracket; 14 is a pin or rod; 15 is a small cylindrical component; 16 is a horizontal bar; 17 is a vertical pin; 18 is a circular plate; 19 is a central shaft or pin; 20 is a lower circular plate; 21 is a top circular plate; 22 is a horizontal arm; 23 is a small cylindrical component; and 24 is a small cylindrical component. Dashed lines indicate the assembly path and alignment of the parts.

Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 14




Fig. 11




Fig. 12






Fig. 13




Fig. 15




Fig. 16




Fig. 17